United States of America

Department of Transportation -- Hederal Abiation Administration

Supplemental Type Certificate

Number SA00024NY

This certificate issued to

Airwolf Filter Corp. 12801 Hwy 75 North Okmulgee, OK 74447

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.

Original Product—Type Certificate Number: * See attached FAA Approved Model List

Make:

* (AML) No. SA00024NY for list of approved

Model:

* airplane models and applicable installation instructions)

Description of Type Design Change:

Installation of Airwolf remote mounted engine oil filter kit AFC-K007 on single or multi-engine fixed wing light aircraft incorporating Lycoming reciprocating engines of 450 horsepower or less.

Limitations and Conditions:

- 1. Engine compartment firewall for mounting oil filter shall be of 0.021 inch minimum thickness ASTM A527 galvanized steel or equivalent Ref. CAR 3.624(b), FAR 23.1191(h).
- Airwolf Instructions for Continued Airworthiness, AFC-K000-ICA, revision IR, dated July 5, 2012 or later FAA accepted revision is required with this installation.
- Compatibility of this design change with previously approved modifications must be determined by the installer
- 4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: June 08, 1993

Date of issuance: July 22, 1993

Date reissued: December 20, 2017

Date amended: 11/11/93, 2/3/94, 11/22/94, 5/25/95, 2/5/96, 5/23/97, 7/21/99, 10/3/2012

By direction of the Administrator



(Signature)

Roy E. Boffo Manager, Propulsion and Program Management Section Chicago ACO Branch

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.